

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-06442INITIAL
JJMCUSTOMER ORDER NO.
32877DATE RECEIVED
02/21/92DATE OPENED
03/02/92DATE CODE
KA 5-80SERIAL NUMBER
B622720

NEW SERIAL NUMBER

MODEL AND GRADE
700 30-06

BDL

ACCESSORIES

W/STUDS

FROM:

SHOOTIN SHACK INC
1065 SILVER BEACH ROAD
RIVIERA BCH

FL 33403

SHIP TO:

SHOOTIN SHACK INC
1065 SILVER BEACH ROAD
RIVIERA BCH

FL 33403

CUST NO: 028463 C.J.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C.

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Customer says "Gun fired upon
closing of Bolt" ---
Cannot duplicate complaint --- rifling trigger assembly of
properly in early report.

Trigger pull 5 1/2 pounds; rear-left .010"

PARTS

COMMENTS

Offer to return rifle as-is, or
to replace trigger assembly at a
nominal cost, as a gesture of good-
will, if that will better restore
confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTEI

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8

PPS 04522