

July 9, 1979

The Shooting Shop
P. O. Box 191
Jefferson City, Tennessee 37760

Gentlemen:

Examination has been completed on the Model 700BDL 25-06 caliber rifle, Serial #6851803, which allegedly fired accidentally.

Our experts examined the rifle and trigger assembly and could not duplicate the incident you described; all parts, tolerances, and dimensions were found to be normal including sear connector engagement. However, it appears that the weight of pull and overall adjustment screws have been altered outside of our Company, as evidenced by the sealant having been removed from them.

Based on our findings, the Remington Arms Company, Inc., cannot, of course, accept any responsibility or liability for the incident. We can only assume that accidental contact was made with the trigger. At this time, very little effort is required to pull the trigger rearward.

We trust that we have clarified the circumstances that would possibly have caused the accidental firing, and as a gesture of customer goodwill, even though there is nothing wrong with your present trigger assembly, we can replace it with another assembly at no charge to insure that your customer's faith in the rifle is restored or the rifle can be returned to you as received. We will await your decision and reply.

Thank you for having afforded us this opportunity to examine your rifle and to be of service.

Sincerely,

REMINGTON ARMS COMPANY, INC.

J. H. Chisnall
Supervisor, Product Service

JHC/jz