

P.I. 7-1 GUN EXAMINATION REPORT NUMBER: 171 MODEL: 100

GENERAL CONDITION: F+1P R #: 2110

INSIDE WORK: RECOIL SPRING STROD DATE: 11-20-70

STOOD 20750 - Hook retracted outside FROM: 5/4/75

FIRE AMMO TYPE: NOT KNOWN Remington 2801-5-37 5.56mm

& CONDITION: 73633 GUN #: 73633

PROOF: REP INSP.: M TEST: 114 CODE: 13 0-1-67

HEADING: OK GA./CAL.: 305

BRECH OPENING: OK CHECKED BY: M-H-70

RECOIL SHOULDERS: OK APPROVED: 9/24 12/21/

CHAMBER: OK APPROVED: 12/21/70

TEST: OK APPROVED: R.B. 12-2

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 12/21/70

B.R. 12 - METAL CY REC. 1001 WAJ 02-107 10/12/71

10 - TRIGGER? COIL AND ALL

4 1/2 LB TRIC PULL

COMPLAINT: FIRE WHEN COIL DIVS

INCIDENT:

COMMENTS: Passed Trick test. Trigger Pull 4 1/2 #

Gun involved in recall program.

N/39

Recall for control under recall program