

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO

WOG 1 OF 2

RECEIVED 2/13/85	DATE OPENED 12/30/85	DATE CODE Z 11-75	SERIAL NO. A 6221539	MODEL AND GRADE 700 30-06	BDL	ORDER 86-00308
---------------------	-------------------------	----------------------	-------------------------	------------------------------	-----	-------------------

SCOPE MOUNTING SWIVEL STUD

DM:

SHIP TO:

VICTOR SISTOK
15 KONLEY DR.
KALISPELL, MT.

59901

AIR CHARGE	INSURANCE	UPS	PARCEL POST	PROM. DATE	ESTIMATED	VIA UPS
				TOTAL \$		

UN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ QUOTE

CUSTOMER'S COMPLAINT

"Gun fires when you close bolt - it also fires when you release the safety"

IN FAULT

trigger assembly adjusted outside of factory, improperly. Also, stock cracked through guard screw allowing barrel action to rotate causing trigger to bind on trigger-guard.

DEMERIT CODE

RTS

replace trigger assembly with bolt-lock safety type replace stock also - all at NO-charge!

remove recoil pad from present stock & return with rifle when work is done.

1/17/86
Jes.

OR COMPUTER REF. ONLY

PROOF

(CLEAN) (TEST) (TARGET)

REPAIRMAN

OFFICE COPY

RD6925

PPS 04571