

Bob Smith Air Conditioning, Inc.

AIR CONDITIONING, HEATING & VENTILATION • INDUSTRIAL, COMMERCIAL & RESIDENTIAL • TACL A000499C

POST OFFICE DRAWER 907

NEDERLAND, TEXAS 77627

OFFICE 409/724-1224


September 22, 1989

Remington Arms Company
Customer Service
Ilion, New York 13357


I have a Model 700-BDL Remington 30/06 caliber rifle Serial Number A6426006. I have had this rifle for several years but have not hunted with it until 1988. On the opening morning of deer season I loaded the rifle and when I moved the safety from the firing position to the safety position the rifle discharged. I cleaned the rifle put it up and have not used it since; as I am afraid a similiar situation may occur again.

Please advise me if this is an on going problem or what should I do about it.

Sincerely,



BOB SMITH-PRESIDENT
BOB SMITH AIR CONDITIONING, INC.



Please return to Bobby D. Smith
1103 Helena Avenue
Nederland, Texas 77627
409-724-1224