

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-15077

INITIAL CUSTOMER ORDER NO.

CALL TAG ATTN: TOM NAGLE

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

05/05/94

05/05/94

XU 12-71

6508205

700

22-250

BDL/VAR

ACCESSORIES

W/STUDS

L/REAR SIGHT

FROM:

SHIP TO:

SMITH, GEORGE J.
8560 W. 10 RD.
MESICK

MI 49668

SMITH, GEORGE J.
8560 W. 10 RD.
MESICK

MI 49668

CUST NO: 096968 GLO.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE 20.00
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP					E1	F1
BOLT ASSY.					E2	F2
BARREL ASSY.				D1	E3	F3
REC. ASSY.					E4	F4
WOOD			C1	E5		F5
METAL			C2			

MAIN FAULT

Upon receipt, we were unable to duplicate the customer concern. Examination reveals that the cam engagement has been set out and is visible outside the factory. The problem is missing from the original record and the trigger assembly was then in no condition present on trigger.

PARTS

COMMENTS

Revised cam set trigger assembly at 1/2 normal engagement set. as per spec. & good and.

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94