

Sear Lift .0075

Trig Bull 4.5 lbs

Sear engagement have been re-set
and re-installed outside of factory

Sealant is missing from overtone
screw and Trig adjusting screw.

There is no overtone present in
Trig.