

RECEIVING AND ESTIMATING REPORT

INITIAL CS		CUSTOMER ORDER NO.		COMMENTS					
DATE RECEIVED 12/05/90	DATE OPENED 12/11/90	DATE CODE KI 5-98	SERIAL NUMBER A6306546	MODEL AND GRADE 700 243 BDL			ORDER R 90-32111		
ACCESSORIES W/STUDS		SCOPE BASE L/REAR SIGHT							
FROM: SMITH GUNS 5458 PADRE STAPLES MALL CORPUS CHRISTI TX 78411				SHIP TO: SMITH GUNS 5458 PADRE STAPLES MALL CORPUS CHRISTI TX 78411					
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS			

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☒ MARRED

CUSTOMER'S REQUEST: *fires on safety release*

MAIN FAULT: *Find no fault - cannot duplicate complaint. Trigger and safety assembly operates properly. Trigger pull 5 1/2 pounds, consistent .008". However, trigger assembly is contaminated with excess amount of partially dried and wet lubrication.*

PARTS	<i>Offer to return rifle with present trigger assembly (after cleaning) or, we can install a new trigger assembly at ± normal cost, as a gesture of good-will, if it will better restore confidence in the rifle.</i>					
REPAIRMAN BWT	PROOF	CLEAN	TEST	TARGET	PATTERN	
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	

OFFICE COPY

RD6925 REV. 7/90

PPS 04599