Smith's Guns, Inc. 5458 Padre Staples Mali Corpus Christi, Texas 78411 October 22, 1992

Remington Arms Service Division 14 Hoelfler Ave. Ilion, NY 13357

Dear Remington.

Enclosed is a Remington 700 BDL that needs repair and refinishing. The serial number is 6337512. The rifle will not cock unless the safety is engaged, then it will fire when the safety is released. Please repair this problem. The customer also want the rifle to be reblued.

Please repair this rifle and return it to the address above upon completion. Either bill us for the repair cost or notify us and we can prepay.

Sincerely,

Sean P. Smith, Manager