

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-22695

INITIAL PS	CUSTOMER ORDER NO.				
DATE RECEIVED 0/16/92	DATE OPENED 10/21/92	DATE CODE RT 11-70	SERIAL NUMBER 6375433	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MM MAG BDL
ACCESSORIES					

L/STUDS

FROM:	SHIP TO:
SMITH, JIM ADVANCED ELEC. EQUIP. SERV. 2411 LARSON ST. LACROSSE WI 54603	SMITH, JIM ADVANCED ELEC. EQUIP. SERV. 2411 LARSON ST. LACROSSE WI 54603

CUST NO:068571 C.O.D L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	---	------------	-----------	------------

UN CONDITION	REPAIR CHARGE
☐ NEW	EXCISE
☐ LIGHTLY WORN	TAX
☐ WORN	INSURANCE
☐ VERY WORN	UPS
☐ UNREPAIRABLE	PARCEL POST
☐ MARRED	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
RIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT No fault found - cannot duplicate complaint after many attempts. Rifle goes together, assembly operates properly. However, over-travel has been adjusted, certainly factory and is insufficient. Also, it was noted that the bolt stop when lever is broken at the finger piece trigger pull 3 1/2 pounds; rear lift 100#

ARTS	COMMENTS
	Offer the following option:
	1) to return rifle as is, re-adjusting over-travel.
	2) to install new trigger assembly at 1/2 normal cost, as a gesture of good-will if that would better restore confidence in the rifle.
REPAIRMAN FB	PROOF
GALLERY TESTER	DATE
CLEAN	DATE
TEST	DATE
TARGET	DATE
PATTERN	DATE

OFFICE COPY

RD6925 REV. 1/92

PPS 04604