

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-06904

INITIAL CUSTOMER ORDER NO.

JJM

SAFTEY LEVER BROKEN

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

02/17/94

02/24/94

PX 6-73

6649099

700 243

ADL

ACCESSORIES

W/STUDS

FROM:

SHIP TO:

SMITH, WALTER
3209 LUANN DR
ANTIOCH

TN 37013

SMITH, WALTER
3209 LUANN DR
ANTIOCHTN
37013

CUST NO: 092922 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

85.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D2

E4

F4

METAL

C2

D3

E5

F5

MAIN FAULT

Upon receipt, safety assembly would not move from the fire to on/off position. Examination reveals that the engagement pins have been set, and the bottom edges of the rear safety lever have been ground. Action must trigger assembly moved with heavy pressure.

PARTS

COMMENTS

Replace complete trigger assembly & clean action at 1/2 normal replacement cost.

Go ahead called customer - he paid for work done on a gun with

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 04641