

*Received letter  
5/29/85 -  
Responded to letter  
5/29/85  
Jastel*

February 28, 1985

Remington Arms Co.  
Department CB  
939 Barnum Avenue  
Bridgeport, Connecticut 06602

Attention Service Department:

I would like your help with a problem I experienced recently with my Remington Model 600, 6mm rifle. During a recent hunting trip, when jarred slightly, the rifle discharged while the safety was in the "on" position. Fortunately, there were no injuries, although the bullet went through the trunk of my car.

The gun was purchased new in 1976 or 1977 (I can furnish the purchase record, if needed). I have not had this problem or any other related to trigger release since purchasing the rifle. The trigger has not been adjusted or worked while I've owned the gun.

Please advise me of what can be done to prevent the problem in the future.

Sincerely,

*Walt Smith*  
Walt Smith

SERIAL # A6430018

Walt Smith  
3541 Leathertop  
Plano, Texas 75075

*ILION*

RECEIVED  
MAY 20 1985  
K. D. GREEN