

P.I. No GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 BDL  
GENERAL CONDITION: Good R #: 026555  
OUTSIDE WORK: SCOPE MOUNTED DATE: 12-18-72  
FROM: SO. WIS. SPT. CENT.  
FIRED AMMO TYPE: - BELoit, WIS.  
& CONDITION: \_\_\_\_\_ GUN #: 6580387  
ASSEMBLER 73  
PROOF: R.E.P.-B INSP.: 73 TEST: 97 CODE: OW = 7/72  
HEADING: O.K. GA./CAL.: 3006  
BREECH OPENING: - CHECKED BY: C. PROSSER  
RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_  
CHAMBER: O.K. APPROVED: \_\_\_\_\_  
TEST: No APPROVED: \_\_\_\_\_  
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

HEAVY LUBRICANT AROUND SEAR, BURR AT REAR OF  
HOUSING FROM FIRING PIN HEAD.

COMPLAINT: "FIRES SOMETIMES WITH SAFETY ON"

INCIDENT: PROBABLY FOLLOW-DOWN.

COMMENTS: THE HEAVY LUBRICANT COMBINED WITH SEAR-  
BIND PROBABLY HELD THE SEAR IN FIRED POSITION  
AND CAUSED FOLLOW-DOWN.