

Cust. Comp.

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: NEW R #: 020090
OUTSIDE WORK: SCOPE MOUNTED DATE: 10-10-72
FROM: SOUTHERN GUN DIST ^{INC.}
FIRED AMMO TYPE: W-W SUPER MIAMI, FLORIDA
& CONDITION: _____ GUN #: 6562968
PROOF: R.E.P.-M INSP.: 73 TEST: 59 CODE: KW=5/72
HEADING: _____ GA./CAL.: 7MM REM. MAG.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .020, STEEL
SHAVINGS BETWEEN SEAR AND HOUSING AT SEAR PIN
HOLE.

COMPLAINT: FIRES WHEN CLOSING BOLT

INCIDENT: FOLLOW DOWN.

COMMENTS: THE STEEL SHAVINGS PROBABLY CAUSED THE
SEAR TO BIND AND FAIL TO RETRACT TO COCKED
POSITION THUS, FOLLOW DOWN.