

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO. 4244		COMMENTS		R91-12048	
DATE RECEIVED 06/03/91	DATE OPENED 06/06/91	DATE CODE XE 12-84	SERIAL NUMBER B6654605	MODEL AND GRADE 700 30-06	ADL	ORDER R 91-1204	
ACCESSORIES W/STUDS		L/REAR SIGHT					

FROM:	SHIP TO:
SOUTHLAND GUN WORKS, INC. 1134 HARTSVILLE RD. DARLINGTON SC 29532 USA	SOUTHLAND GUN WORKS, INC. 1134 HARTSVILLE RD. DARLINGTON SC 29532 USA

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 6-17-91	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	----------------------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: *Gun fired when safety was disengaged*

MAIN FAULT: *Cannot duplicate complaint, however, disassembly of rifle reveals bottom of receiver, trigger assembly, barrel and magazine follower spring were rusty - rifle had been wet at some time and not properly maintained. Trigger pull 5 1/2 pounds; was left "012" safety "off" for heavier than normal.*

PARTS: *Based on heavy safety "off" force, replace trigger assembly at no-charge. Cleaning of rifle should be charged.*

REPAIRMAN RBA	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/8