

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO. "B"		COMMENTS L SIGHT ON REAR RAMP		ORDER 88-12950	
DATE RECEIVED 04/26/88	DATE OPENED 05/05/88	DATE CODE AW 3-72	SERIAL NUMBER 6539015	MODEL AND GRADE 700 243	R
ACCESSORIES L/WOOD		SCOPE BASE			

FROM:	SHIP TO:
VICTOR E SPEAR R R # 2 BOX 61 CHURUBUSCO IN 46723	VICTOR E SPEAR R R # 2 BOX 61 CHURUBUSCO IN 46723

ACCOUNT NUMBER	FROM DATE	ESTIMATED	VIA UPS
REPAIR CHARGE	TAX ST	INSURANCE	UPS
TAX CITY	PARCEL POST	TOTAL	\$

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ QUOTE

CUSTOMER'S COMPLAINT
"almost every time the butt is hit down it fires and also when the safety is released it fires".

MAIN FAULT
Trigger has been grossly misadjusted outside factory - trigger pull @ 1 pound, rear engagement so misadjusted, rifle will not cock most of the time.

PARTS
Send repair quotation to either re-adjust trigger or replace trigger assembly, whichever is necessary.

5/9/88
JLS

FOR COMPUTER REF. ONLY	PROOF
	(CLEAN) (TEST) (TARGET)
	REPAIRMAN <i>T.P.S.</i>