

Stake

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO.		COMMENTS			
100		L SIGHT ON REAR RAMP			
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
4/16/81	4/15/81	AW 72	4539015	700 743	R 88-12950
ACCESSORIES					

FROM:	SHIP TO:
	VILLAGE OF ...
	...
	...
	...

ACCOUNT NUMBER	FROM DATE	ESTIMATED	VIA		
063103		5-23-81			
REPAIR CHARGE	TAX STATE	INSURANCE	UPS	PARCEL POST	TOTAL
35.00	5/10/75		3.44		40.19
TAX CITY					

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☒ QUOTE

CUSTOMER'S COMPLAINT
"almost every time the butt is let down it fires and also when the safety is released it fires".

MAIN FAULT
Trigger has been grossly misadjusted outside factory - trigger pull $\approx$ 1 pound, cam engagement is misadjusted, rifle will not cock most of the time.

PARTS *26345*
Trigger Assy B.C. desired repair quotation to either readjust trigger or replace trigger assembly, whichever is necessary.

4 to 6 weeks

polished chamber 5/17/81
check headspace etc.

FOR COMPUTER REF. ONLY		PROOF
		(CLEAN) (TEST) (TARGET)
		REPAIRMAN <i>ML</i>

OFFICE COPY