

RECEIVING AND ESTIMATING REPORT ✓

INITIAL FPS		CUSTOMER ORDER NO. 068182		COMMENTS STK & BBL NOT OUR MFG			
DATE RECEIVED 01/16/91	DATE OPENED 01/24/91	DATE CODE	SERIAL NUMBER B6879036	MODEL AND GRADE 700 458 WIN MAG		ORDER R 91-024	
ACCESSORIES SCOPE BASE W/STUDS							

FROM:

SPORT CENTER
211 E CRYSTAL AVE
LAKE WALES

FL 33853

SHIP TO:

SPORT CENTER
211 E CRYSTAL AVE
LAKE WALES

FL 33853

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

1) fires when bolt closes, 2) don't feed from magazine

MAIN FAULT
1) Cannot duplicate complaint, however, trigger assembly has been improperly adjusted outside of factory (evidenced by red color sealant) insufficient rear trigger pull min spec. of 3 pounds. 2) This action was originally a different Remington caliber ~~caliber~~ apparently of the feed-rail carb won't handle the 458 Win Mag caliber.

PARTS	1) Sent quotation for new trigger assembly at 1/2 formal cost, as gesture of good-will					
	2) We cannot modify the feed rails					
	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/5

PPS 04718