

ESTIMATING REPORT

SPORT CENTER
211 EAST CRYSTAL AVE.
LAKE WALES, FLA. 33853

MAG R ORDER
 91-024

Customer's Order No. _____ Date 1-2 1990
 Name Remington Arms Co.
 Address _____

SHIP TO:
 SPORT CENTER
 211 E CRYSTAL AVE
 LAKE WALES FL 33853

PROM. DATE _____ ESTIMATED _____ VIA UPS

SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	MO. RET.	PAID OUT
---------	------	--------	--------	----------	----------	----------

QUAN.	DESCRIPTION	PRICE	AMOUNT
	<i>Please find enclosed</i>		
	<i>Custom 700 BDL</i>		
	<i>488- B6879036</i>		
	<i>① gun fires when bolt closed-</i>		
	<i>② gun does not feed well from mag.</i>		
	<i>Thank You</i>		

PARCEL POST TOTAL

☐ MISUSED ☐ MARRED

feed from magazine
gun assembly has been inspected
1) insufficient rear engagement
was originally a different
feed-rail cut would
ation for new trigger assembly
cost, as gesture of

All claims and returned goods MUST be accompanied by this bill.

368182 RECEIVED BY Lloyd TAX TOTAL

Universal ES-55582 59395-84

defy the feed rails

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 7/90

OFFICE COPY

PPS 04719