

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: USED R #: 22448
OUTSIDE WORK: SCOPE MOUNTED DATE: 11-8-71
FROM: THE SPORTSMAN
FIRED AMMO TYPE: - HARLINGEN, TEXAS
& CONDITION: _____ GUN #: 276664
PROOF: R.E.P. ASSEMBLER 64 INSP.: 9 TEST: 87 CODE: RP= 5/67, OT 3= 7/70
HEADING: _____ GR./CAL.: 7MM 0.280
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED, OR BROKEN COMPONENTS

TRIGGER BINDS ON GUARD. TRIGGER PULL 2 1/2 POUNDS.

COMPLAINT: "FIRES WHEN SAFETY IS PUT IN FIRE POSITION"

INCIDENT: FOLLOWS DOWN

COMMENTS: WITH THE TRIGGER PULL LIGHT (2 1/2 POUNDS) AND THE
TRIGGER BINDING ON THE GUARD, IT IS POSSIBLE THAT
TRIGGER-CONNECTOR RETRACTION WOULD BE ERRATIC.
THIS COULD CAUSE FOLLOW ON DOWN WHEN THE TRIGGER
IS PULLED WITH THE SAFETY ON.