

Curt Campbell

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 002158
OUTSIDE WORK: SCOPE MOUNTED DATE: 1-23-73
FROM: SPORTSMAN'S HEADQUARTERS
FIRED AMMO TYPE: - GRANDFORKS, N.D.
& CONDITION: _____ GUN #: 6451849
PROOF: R.E.P.-L INSP.: 9 TEST: 53 CODE: PU-6/71
HEADING: O.K. GA./CAL.: 2006
BREECH OPENING: - CHECKED BY: G. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

HOUSING=.069 AT TOP (MODEL DRAWING: 173) TRIGGER
.173 LOWER END (MODEL DRAWING: 170) METAL CHIPS
AROUND PIN HOLE ON TRIGGER. SEAR-TRIGGER
CONNECTOR ENGAGEMENT .010 (MIN. IS .020)

COMPLAINT: "WILL FIRE WHILE REMOVING UNFIRED SHELL
FROM THE CHAMBER"

INCIDENT: FOLLOW DOWN.

COMMENTS: THE CUSTOMER'S MALFUNCTION NOT DUPLICATED.
THE BINDING TRIGGER AND SEAR FAILING TO RETRACT
ALONG WITH UNDER MIN. ENGAGEMENT PROBABLY
CAUSED THE FOLLOW DOWN.