

P.I. NO GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 *Cust. Ample*

GENERAL CONDITION: NEW

R #: 013117

OUTSIDE WORK: SCOPE MOUNTED

DATE: 6-19-72

FIRE AMMO TYPE: -

FROM: SPORTSMEN'S DEN
MT. SHASTA, CAL.

& CONDITION: _____

GUN #: 6249832

PROOF: R.F.P.-D INSP.: 74 TEST: 87

CODE: PS-6/69, CH.3-4/72

HEADING: O.K.

GA./CAL.: 7MM

BREECH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN.=.020)
BOTH SEAR AND CONNECTOR DAMAGED ON ENGAGEMENT
CORNERS. CONDITION OF FIRING PIN HOLE & FIRING PIN
POINT INDICATE PRIMER PIERCING HAS BEEN EXPERIENCED.

COMPLAINT: WILL NOT FIRE

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER PROBABLY EXPERIENCED A PIERCED
PRIMER WHICH WITH THE .010 ENGAGEMENT, CAUSED THE
SEAR-CONNECTOR DAMAGE RESULTING IN FOLLOW-
DOWN.