

P.I. YES GUN EXAMINATION REPORT NUMBER: 215

GENERAL CONDITION: FAIR

OUTSIDE WORK: SCOPES SCREWED REMOVED

FIRED AMMO TYPE: 105 - 4400WV

& CONDITION: _____

PROF: (PEP) INSP.: 130 TEST: 57

HEADING: OK

BREACH OPENING: OK

RECOIL SHOULDERS: OK

CHAMBER: OK

TEST: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

SLIGHT MARKS IN WOOD

METAL BRIGHT ON RBL. FLOOR PLATE

AND B-LT.

COMPLAINT: ACCIDENTALLY DISCHARGED TWICE

INCIDENT: _____

COMMENTS:

- { Bolt stop release would not work.
- Trigger control extremely full of oil & crud.
- Trigger pull 7 3/4# - Passed twist test.
- Trigger adjusting screw head damaged - appears to have been adjusted out side of factory and reversed.

MODEL: 700 RBL

R #: 00626

DATE: 1-3-80

FROM: FAVOR STAVELAND

Fig 53
Col 0032 - 100

GUN #: A1271784

CODE: AI-3-76

GA./CAL.: 3006

CHECKED BY: LI-44804

APPROVED: SN 3/25/80

APPROVED: JL 3/25/80

APPROVED: R.B. 3-25-80

APPROVED: VED 3-25-80
200 - 2100