

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R93-10747

INITIAL CUSTOMER ORDER NO.

ATTN: DENNIS SANITA
W/BTM PART OF SCOPE MNTS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

1/26/93

04/27/93

CQ 4-78

A6591981

700 25-06

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

FROM:

SHIP TO:

STANLEY, DAVID
112 TEXAS AVE
P O BOX 427
HEWITT

TX 76643

STANLEY, DAVID
112 TEXAS AVE
P O BOX 427
HEWITTTX
76643

CUST NO: 078557 C.O.D

COUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

CONDITION

NEW

LIGHTLY WORN

WORN

VERY WORN

UNREPAIRABLE

REPAIRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

LE

A1

B1

TRIGGER GROUP

B2

TRIGGER ASSY.

B3

REL ASSY.

B4

ASSY.

B5

D

C1

D3

L

C2

FAULT

Unable to duplicate Customer Concern. However, observation revealed trigger group, trigger assembly on both sides when action, and trigger housing are adjusted and the trigger stop screw appears to have been in correct position. Adjusting adjustment screws have been attempted with.

Trigger had 4 1/2 lbs.
in left .008

COMMENTS

Left trigger assembly
and observation at 1/2 second
replacement cost, as given by you
will.

For record

GALLERY MAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92

PPS 04850