

# RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 92-07812

INITIAL JJM CUSTOMER ORDER NO.

DATE RECEIVED 04/06/92 DATE OPENED 04/13/92 DATE CODE QV 7-79 SERIAL NUMBER A6791557 NEW SERIAL NUMBER MODEL AND GRADE 700 30-06 BDL

ACCESSORIES W/STUDS SCOPE BASE L/REAR SIGHT

FROM: ST LAURENT, DAVID 585 KEELING RD NORTH POLE AK 99705  
SHIP TO: ST LAURENT, DAVID 585 KEELING RD NORTH POLE AK 99705

CUST NO: 060810 C-D.D

ACCOUNT NUMBER ACCOUNT NUMBER N/C WRITE ☐ CLEAN/TEST PROM. DATE ESTIMATED VIA UPS

|                                       |               |
|---------------------------------------|---------------|
| GUN CONDITION                         | REPAIR CHARGE |
| <input type="checkbox"/> NEW          | EXCISE        |
| <input type="checkbox"/> LIGHTLY WORN | TAX           |
| <input type="checkbox"/> WORN         | INSURANCE     |
| <input type="checkbox"/> VERY WORN    | UPS           |
| <input type="checkbox"/> UNREPAIRABLE | PARCEL POST   |
| <input type="checkbox"/> MARRED       | TOTAL         |

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|------------------|------|----------|--------|----------|-----|---------|
| CYCLE            | A1   | B1       |        |          |     |         |
| TRIGGER GROUP    |      | B2       |        |          |     |         |
| BOLT ASSY.       |      | B3       |        | E2       | F2  |         |
| BARREL ASSY.     |      |          | D1     | E3       | F3  |         |
| REC. ASSY.       |      | B5       | D2     | E4       | F4  |         |
| WOOD             |      |          | C1     | D3       | E5  | F5      |
| METAL            |      |          | C2     |          |     |         |

MAIN FAULT Cannot duplicate complaint - trigger assembly and adj operate properly. Probably w/ upr. shown trigger assembly. When pulled outwards to factory trigger pull adjustment has changed (replant removed) trigger pull allow ckb spec. measure at 3 pounds.

Trigger pull 3 pounds; acc. lift .009"

PARTS COMMENTS Offer to re-adjust present action to specification, or we can install a new trigger assembly at normal cost as a gesture of good-will if that will better restore confidence in the rifle.

REPAIRMAN PROOF CLEAN TEST TARGET PATTERN  
GALLERY TESTER DATE DATE DATE DATE DATE DATE