

RECEIVING AND ESTIMATING REPORT

CUST NO: 048532 C.O.D		COMMENTS ATTN J STEKL W/WILLIAMS REAR SIGHT	
CUSTOMER ORDER NO.			
CEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER
03/91	09/04/91	OR 7-68	118833
MODEL AND GRADE		MAG	
660 350REM			
ORDER			
R			91-17410

SCOPE BASE

SHIP TO:	
STOKLEY, MIDGE P O BOX 792 (1 MILE HAINES HWY) HAINES USA	AK 99827

NT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
--------	-----	-----------	-----	-------------	-------

CONDITION:	☐ NEW	☐ SLIGHTLY WORN	☐ VERY WORN	☐ MISUSED	☐ MARRED
------------	------------------------------	--	------------------------------------	----------------------------------	---------------------------------

VER'S REQUEST

"...after... the rifle was released".

AULT: Complaint to complainant. Disassembly of rifle showed the following:
1) Trigger assembly is faulty, to below minimum spec. (2 3/4 mm. 6), as a
result trigger is not positive. 2) Firing pin and spring are rusted
and in need of oil. 3) Trigger assembly is contaminated with excessive lubrication
oil, which with cold temperatures could cause a problem.

1) replace the trigger assembly per m/p 660
2) Clean firing pin assembly

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE