

Speed Message

To Remington Arms Co. Inc.
Product Service Dept
■ Att: Mr. Jim Stekl
14 Hoefler Ave
■ Ilion, New York 13357

From Ladell Sump
■ 104 Lindsey
■ Bay City, Tx 77414

Subject Return of Mohawk 600 Rifle

Date 8-3-89 19__

This rifle was sent off by our dealer for the "fix" of this firing
problem. The mark "V" is on the trigger housing...

I called you in July about another misfire when loading on this
rifle.. This is since being fixed.....

You requested me to send to you for your inspection....

Yours truly,

Ladell Sump

Signed _____

Wilson Jones
MANUFACTURED IN U.S.A.
Carbonless

88

Remington Arms Co., Inc
Product Service Dept.
Att: Jim Stekl
14 Hoefler Ave.
Ilion, New York, 13357

(Note inside)