

Remington-Union

REMINGTON NEW GUN REPAIR INVOICE

REMINGTON-UNION, INC.
BRIDGEPORT, TEXAS 77602

Remington Recommended Gunsmith

Name FREER GUN SHOP
Address 8926 Spring Branch Dr.
City Houston State Tx Zip 77080

Customer's Name David Sunkle
Street 4315 Steffanie
City Houston State Tx Zip 77041

<u>Date Firearm Received</u>		<u>Date Returned to Customer</u>		<u>Returned to Factory</u>	
11-19-79		11-20-79		<u>Date</u>	<u>Via</u>
<u>Model</u>	<u>Cal. or Gauge</u>	<u>Grade</u>	<u>Serial Number</u>		
700	30/06		A6555031 Code BQ		

Complete Description of Customer's Complaint

New gun, fired on closing bolt.

No evidence of any tampering after leaving the factory.



<u>Repairs Performed - Describe in detail</u>	<u>Repair Charge Breakdown</u>
Trigger/sear engagement too short.	Parts \$
Adjusted trigger engagement & pull	Labor 10.00
	Test Ammunition 1.50
	Transportation
	Total \$ 11.50

DISBURSEMENT
JAN 21 1980
AUDIT

Approvals in Order:

1. Field Representative

2. Regional Manager

3. Arms Service (2)

Date: _____

Date: _____

Date: 12/17/79

RD 701, REM 0071

FIELD REPRESENTATIVE IN YOUR AREA

J 23