

RECEIVING AND ESTIMATING REPORT

CUST NO: 008237 WILM		COMMENTS			
INITIAL JJM	CUSTOMER ORDER NO.				
DATE RECEIVED 10/10/91	DATE OPENED 10/14/91	DATE CODE	SERIAL NUMBER A6225033	MODEL AND GRADE 700 6MM	ORDER R 91-20632
ACCESSORIES		W/STUDS		SCOPE BASE	
			XZ 12-75 2ND TIME IN		

FROM:	SHIP TO:
SUPERIOR SHOOTERS SUPPLY 1705 WINTER SUPERIOR USA WI 54880	SUPERIOR SHOOTERS SUPPLY 1705 WINTER SUPERIOR USA WI 54880

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	---	------------	-----------	------------

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST *fires on closing
" when safety is moved*

MAIN FAULT *Cannot duplicate above complaints. However, trigger parts movement is slow, due to contamination of inside of trigger assembly of gummy residue. Trigger assembly, which within gun, has been subjected outside today, as evidenced by red sealant on adj. screws. Trigger pull 3 pounds; over-throw .013". Improper maintenance.*

Clean present trigger assembly, if possible. If not, send gun for new assembly at 1/2 retail cost, as gesture of good will.

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

REV 7/00