

RRR - 113

Gentlemen

Please Replace And/or Repair the
Trigger Assy on this Rem 700 BDL.
Ser. # A 6376 164.

My original problem was that the
Rifle would sometimes fire when taken
off safety. Upon examination I found
that the trigger connector would sometimes
hang point to point on the sear. This
would allow it to fire when taken off safety.

Thank you

Willie Short
P.O. Box 150 A
Pittsburg, Texas 75755

5 74 043 08-22-21964