

RECEIVING AND ESTIMATING REPORT

PROM. DATE _____

ORDER R 11474

DATE RECEIVED _____ ESTIMATED _____

DATE OPENED 5-8-85 VIA JPSMODEL AND GRADE 700ADL - 22-250 SERIAL NO. 6422056DATE CODE CU4-71

FROM:

R.M. Tanner
Farmers Service Center
P.O. Box 252
Madison, VA. 22727

REPAIR CHARGE _____

INS. _____

UPS _____

PARCEL POST _____

TOTAL \$ _____

GUN CONDITION: (NEW) (SLIGHTLY WORN) (VERY WORN) (MISUSED) (QUOTE)

CUSTOMER'S COMPLAINT "When you close the bolt, and take safety off. the gun fires, without touching trigger"

MAIN FAULT Trigger very loose on pivot pin - retention not positive. In addition, inside of Assembly has excess dried lubrication.

DEMERIT
CODE

PARTS _____

replace trigger assembly
at no-charge.

5/8/85

JAS.

FOR COMPUTER REFER. ONLY

PROOF _____

(CLEAN) (TEST) (TARGET)