

RECEIVING AND ESTIMATING REPORT

COMMENTS

to Product Service

R

ORDER
94-09925

CUSTOMER ORDER NO.

FP5

RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

3/16/94

03/17/94

WJU

B-49

81493

721

30-06

SSORIES

W/STUDS

SCOPE BASE

Fred Supply

SHIP TO:

TARABORIS WELDING SHOP
73 RIVER ST
GALETON

PA 16922

TARABORIS WELDING SHOP
73 RIVER ST
GALETON

PA 16922

CUST NO:052546 C.I.O.D.

UNIT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

CONDITION

EW

GHTLY WORN

ORN

ERY WORN

NREPAIRABLE

ARRED

REPAIR CHARGE

20

EXCISE

TAX

INSURANCE

UPS

8

PARCEL POST

TOTAL

28.00

TOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
E	A1	<i>Safety releases too easily and on</i>				
GER GROUP		B2		E1	F1	
ASSY.		B3		E2	F2	
IEL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
D			C1	D3	E5	F5
IL			C2			

FAULT: Mfg. 8-49 off safe force is very light. Other than easy off safe trigger worked properly in every respect. Trigger has been adjusted outside of the factory. Replace trigger assy with modified 700 trigger assy. at a special price strictly as a gesture of good will and to restore customers confidence in the rifle.

COMMENTS

Trigger pull measured 5# as rec'd and safe lift was .0105

Check ^{new} trigger assy for proper clearances and function

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 04992