

NOV. 29, 1991

To Whom It May Concern:

ENCLOSED IS (1) ONE REMINGTON Model 700
6MM., SERIAL # B6712840.

I HAVE (2) TWO PROBLEMS. FIRST AND OF
UTMOST IMPORTANCE, ON OCCASION THIS RIFLE
WILL DISCHARGE WHILE PUSHING THE SAFETY
FROM THE ON POSITION TO THE OFF POSITION.
THESE ACCIDENTAL DISCHARGES OCCURRED
WITHOUT MY FINGER ON THE TRIGGER.

SECONDLY, I HAVE NEVER FIRED BETTER
THAN A 3"4" GROUP AT 100YDS, NOR HAS
ANYONE ELSE DONE ANY BETTER.

I AM REQUESTING THAT THE SAFETY MECHANISM
BE FIXED AND WHATEVER NEEDS TO BE DONE
TO CORRECT THE ACCURACY OF THIS RIFLE.

PLEASE BILL ME FOR ANY COSTS OF REPAIRS
WHICH WILL NOT BE ~~ABS~~ ABSORBED BY THE REMINGTON
ARMS CO

phone # 601-234-3200
FAX # - 601-236-6354

Thanks.
Julian Tutum
P.O. Box 603

University, Ms. 38677
Residence: 135 Leighton Rd.
Oxford, Ms. 38655