cc: K.D. Green DON'T SAY IT-WRITE IT

اه	D.J. SANITA	Location _	ARMS SERVICE 52-2	
tom	J.A. STEKL	Location	PRODUCT SERVICE 52-4	Phone No.
	R#06964 M/700 BDL L.H. 30-06	-		Dat# /6/82

Please replace the trigger assembly on the subject rifle at no-charge and return to:

> American Service Company of Atlanta, Inc. Attn: C. Everett Thomas, Jr., President 2006 Weems Rd. Tucker, Georgia 30084

Please note that this rifle was returned to us by Sportco, Inc., Marietta, Georgia for Thomas.

Please expedite the work and keep the old trigger for possible future reference.

Thank you,

STOP, LOOK, AND LIVE