

RECEIVING AND ESTIMATING REPORT

CUST NO: 050773 C.O.D		COMMENTS			
ITAL PS	CUSTOMER ORDER NO.				
TE RECEIVED 0/07/91	DATE OPENED 10/09/91	DATE CODE WR 8-68	SERIAL NUMBER 365767	MODEL AND GRADE 700 243 WIN	ADL
ACCESSORIES W/STUDS	L/SIGHTS	SCOPE BASE		ORDER R 91-20313	

FROM:	TINSLEY, JACK BOX 183 LIVINGSTON USA		MT 59047	SHIP TO:	TINSLEY, JACK BOX 183 LIVINGSTON USA		MT 59047
-------	---	--	----------	----------	---	--	----------

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 10-18	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	--------------------	------------

--	--	--	--	--	--

AIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
------------	-----	-----------	-----	-------------	-------

IN CONDITION:	☐ NEW	☐ SLIGHTLY WORN	☐ VERY WORN	☐ MISUSED	☐ MARRED
STOMER'S REQUEST	discharged while closing the bolt				

IN FAULT	Cannot duplicate complaint. However, examination of trigger assembly revealed the inside is contaminated with a greasy, sticky substance. The rear-safety cam is not moving properly, due to substance on inside of trigger-side-plate. Trigger pull measured at 4$\frac{3}{4}$ #; rear lift .009"
----------	--

TS	Due to age of rifle, offer new trigger assembly at $\frac{1}{2}$ normal cost as a gesture of good-will					
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN	
BWT						
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	

OFFICE COPY

RD6923 REV. 7/90

PPS 05074