

# RECEIVING AND ESTIMATING REPORT

|                           |                         |                      |                           |                                  |  |                   |  |
|---------------------------|-------------------------|----------------------|---------------------------|----------------------------------|--|-------------------|--|
| INITIAL<br>FPS            |                         | CUSTOMER ORDER NO.   |                           | COMMENTS<br><br>814              |  |                   |  |
| DATE RECEIVED<br>12/11/90 | DATE OPENED<br>12/17/90 | DATE CODE<br>BD 1-77 | SERIAL NUMBER<br>A6408324 | MODEL AND GRADE<br>700 30-06 BDL |  | ORDER<br>R 90-327 |  |
| ACCESSORIES<br>W/STUDS    |                         |                      |                           |                                  |  |                   |  |

|                                                                |                                                                |
|----------------------------------------------------------------|----------------------------------------------------------------|
| FROM:                                                          | SHIP TO:                                                       |
| TOM'S HANDLOADING CENTER<br>45A WINN ST<br>BURLINGTON MA 01803 | TOM'S HANDLOADING CENTER<br>45A WINN ST<br>BURLINGTON MA 01803 |

|                |                    |                                |            |            |                     |            |
|----------------|--------------------|--------------------------------|------------|------------|---------------------|------------|
| ACCOUNT NUMBER | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> | CLEAN/TEST | PROM. DATE | ESTIMATED<br>1-4-91 | VIA<br>UPS |
|----------------|--------------------|--------------------------------|------------|------------|---------------------|------------|

|               |     |           |     |             |       |
|---------------|-----|-----------|-----|-------------|-------|
| REPAIR CHARGE | TAX | INSURANCE | UPS | PARCEL POST | TOTAL |
|---------------|-----|-----------|-----|-------------|-------|

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☒ MARRED <sup>W/O</sup>

CUSTOMER'S REQUEST: inspect and repair - rifle discharged when the safety was put in the "On" position

MAIN FAULT: Cannot duplicate complaint, as by design a m/200 rifle cannot fire with the safety "on" since the firing pin is blocked. Trigger and safety assembly operate properly - trigger pull 4 1/2 pounds; over-  
lift .008". No fault found.

|       |  |                  |  |  |  |       |       |      |        |         |
|-------|--|------------------|--|--|--|-------|-------|------|--------|---------|
| PARTS |  | REPAIRMAN<br>614 |  |  |  | PROOF | CLEAN | TEST | TARGET | PATTERN |
|       |  | GALLERY TESTER   |  |  |  | DATE  | DATE  | DATE | DATE   | DATE    |

Offer to return rifle as-is or, we can install a new trigger assembly at 1/2 normal cost, as a gesture of good-will if it will better restore confidence in the rifle.

OFFICE COPY

RD6925 REV. 7/90

PPS 05081