

# RECEIVING AND ESTIMATING REPORT ✓

INITIAL JLM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 12/07/91	DATE OPENED 02/15/91	DATE CODE DX 9-73	SERIAL NUMBER 6676256	MODEL AND GRADE 700 30-06 ADL		ORDER R 91-0454	
ACCESSORIES W/STUDS							

FROM: TOM'S GUN SHOP 203 EAST MADISSON MEMPHIS MO 63555		SHIP TO: TOM'S GUN SHOP 203 EAST MADISSON MEMPHIS MO 63555	
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/> CLEAN/TEST	PROM. DATE ESTIMATED VIA UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

SUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"Gun will not fire sometimes & gas off when you close bolt sometimes".

MAIN FAULT  
As received, trigger assembly inoperative. Disassembly revealed internal parts of trigger assembly will not move due to contamination by sticky residue. Trigger and connector are sticking to trigger assembly side plates. Rifle has not been properly maintained.

Offer replacement trigger assembly at 1/2 normal cost, as gesture of good-will.

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 05083