

TOM'S SHOOTER'S SUPPLY
THOMAS C. HEINZEL
910 - 6th ST.
ALBANY, MN 55307

1-20-89

ATTN: Service Dept

Enclosed is a defective
Rem 700 BDL LH barrel ACTION
SERIAL # B6237382 in the
7mm Rem Mag CAL.

My customer claims that it
will discharge without even
pulling the trigger. This happened
to him on A Western States
hunting trip, and on the range.

He also stated that he has
had problems chambering rounds,
i.e., two rounds trying to
chamber at the same time.

Please check this out, and
repair accordingly. If there
is a charge, please inform me.
THANK YOU

Sincerely,
TCH