

RECEIVING AND ESTIMATING REPORT

INITIALS

CUSTOMER ORDER NO.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

ACCESSORIES

SLING STRAP

W/STUDS

W/SWIVELS

SOFT CASE

SCOPE BASE

FROM:

TOPHAM, DAVID

31 INDIAN TRAIL

HANSON

MA 02341

SHIP TO:

TOPHAM, DAVID

31 INDIAN TRAIL

HANSON

MA 02341

CUST NO: 060099 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

NEW

LIGHTLY WORN

WORN

VERY WORN

UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

No fault found - trigger assembly and safety operate properly & every report - cannot make light malfunction after 2 hours attempt.

Trigger pull 35 pounds; rear lift on

PARTS

COMMENTS

Offer to return rifle as-is, or, a complete trigger assembly at \$2000 cost, is a question of good-will of the well better restore confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8/91