Dec. 4 1989 Herndon, Pa.

Service Dept. Rem. Arms Co.

Gentlemen,

The enclosed Rem. rifle Model 700 L.H. Caliber 30-06 ,Serial number 68T0005 is being returned for inspection and repair if necessary of the trigger saftey or bolt. The rifle has accidently fired three times for the owner. (See attached note). The customer stated he was using Federal factory loaded ammo.

Harvey Troutson

RETURN TO :

H.A.TROUTMAN GUNS & AMMO R.D.#I, BOX 1627 HERNDON, PA. 17830