

Customer Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: Good R #: 23021
OUTSIDE WORK: SCOPE MOUNTED, TRIGGER DATE: 11-15-71
ADJUSTMENTS CHANGED FROM: WILLIAM H. ULERY
FIRED AMMO TYPE: - OBERLIN, KANSAS.
& CONDITION: ASSEMBLER 73 GUN #: 6456668
PROOF: R.E.P. - 0 INSP.: 73 TEST: 66 CODE: OU = 7/71
HEADING: CLOSES OVER MAX. BELT GAGE. GA./CAL.: 7MM
BREECH OPENING: - CHECKED BY: CIPROSSER
RECOIL SHOULDERS: EXCESSIVE RADIUS AT REAR. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO DAMAGED COMPONENTS.

COMPLAINT: WENT OFF ACCIDENTALLY WHILE UNLOADING, AGAIN LATER
WHILE LOADING.

INCIDENT: FOLLOW DOWN.

COMMENTS: CUSTOMER'S MALFUNCTION NOT VERIFIED BY WRITER,
HOWEVER HIS RE-ADJUSTING HAS MADE IT IMPOSSIBLE TO
DETERMINE WHETHER THE RIFLE WAS CORRECTLY
ADJUSTED ON FINAL ASSEMBLY.