

Since we found the trigger assembly to be outside our specifications, we can either readjust the present assembly or, if it will better restore confidence in the rifle, we will install a new trigger assembly at no-charge as a goodwill gesture. We will await the decision and reply.

Thank you for affording us the opportunity to examine the rifle and report our findings.

Sincerely,

A handwritten signature in dark ink, appearing to read "D.J. Sanita", written in a cursive style.

D.J. Sanita, Specialist
Product Service

DJS:tp

Remington Arms Company, Inc.

PPS 05169