

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL

GENERAL CONDITION: NEW R #: 15003

OUTSIDE WORK: TRIGGER PULL REDUCED TO DATE: 7-30-71

ONE POUND. FROM: UNITED DIST.

FIRE AMMO TYPE: - GALVESTON, TEXAS

& CONDITION: _____ GUN #: 6408400

PROOF: R.E.P. INSP.: 74 TEST: 98 CODE: LO: 2/71

HEADING: O.K. GA./CAL.: 270 WIN.

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: No APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

ADJUSTING SCREW FOR TRIGGER PULL UNSEALED
AND ADJUSTMENT ALTERED.

COMPLAINT: FIRING PIN ENGAGES & FIRES WHEN BOLT IS
PUSHED FORWARD.

INCIDENT: FOLLOW DOWN

COMMENTS: WHEN TRIGGER PULL WAS CORRECTED ENGAGE-
MENT OF SEAR AND TRIGGER CONNECTOR WAS .025-
MIN. IS .015 WITH TRIGGER PULL REDUCED THE
SPRING WILL NOT RETRACT THE TRIGGER CONNECTOR
CORRECTLY AND FOLLOW DOWN MAY RESULT.