

RECEIVING AND ESTIMATING REPORT ✓

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 08/27/90	DATE OPENED 09/06/90	DATE CODE LW 2-72	SERIAL NUMBER 6520098	MODEL AND GRADE 700 25-06 ADL		ORDER R 90-23	
ACCESSORIES W/STUDS		SCOPE BASE					

FROM:

VALLEY GUNS INC.
RT 2 BOX 341
BUNKER HILL WV 25413

SHIP TO:

VALLEY GUNS INC.
RT 2 BOX 341
BUNKER HILL

WV
25413

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"i.e. rifle fired when safety was moved from on-safe to off-safe"

MAIN FAULT

no fault found - trigger assembly operate properly. Trigger has been adjusted outside factory as evidenced by red sediment on all 3 adjustment screws. Trigger pull 3#, was left out.
Cannot duplicate complaint.

PARTS

Offer to return rifle as-is or, as a gesture of good-will offer to replace the trigger assembly at normal price, ~~regardless~~ if it will restore confidence in the rifle.

Rifle is 18 years old

REPAIRMAN TN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV

PPS 05175