

Cust Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL

GENERAL CONDITION: GOOD R # : 027088

OUTSIDE WORK: NO DATE: 12-18-72

FROM: VALLEY HOME SUPPLY ^{CO.}

FIRE AMMO TYPE: - MILESBERG, PA.

& CONDITION: _____ GUN # : 6261266

ASSEMBLER - P

PROOF: R.E.P.-D INSP.: 9 TEST: 13 CODE: OS = 7/69

HEADING: O.K. GR./CAL.: 308 WIN.

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

EVIDENCE OF TRIGGER BURRS BINDING. TRIGGER 1.074

(MODEL DRAWING 1.076) EXCESSIVE LUBRICANT-TOO HEAVY.

TRIGGER CONNECTOR-SEAR ENGAGEMENT .015 (MIN. IS .020)

COMPLAINT: "FIRED WHEN SAFETY WAS RELEASED"

INCIDENT: FOLLOW-DOWN.

COMMENTS: THE TRIGGER BIND, HEAVY LUBRICANT COMBINATION
PROBABLY CAUSED THE FOLLOW DOWN.