

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 92-02993

INITIAL

CUSTOMER ORDER NO.

RJH

W/BUSHNELL SPORTVIEW SCOPE *Stetl*

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/16/92

01/24/92

PE 6-84

B6597087

78

30-06

ACCESSORIES

W/STUDS

SCOPE MNTS

SCOPE BASE

L/REAR SIGHT

FROM:

VAN HORN, RAY L
16 MILLER RD
TAWAS CITY

MI 48763

SHIP TO:

VAN HORN, RAY L
16 MILLER RD
TAWAS CITYMI
48763

CUST NO: 056882 C.D.IX

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

2-10-92

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

BOLT ASSY.

B3

E2

BARREL ASSY.

B4

D1

E3

REC. ASSY.

B5

D2

E4

WOOD

C1

D3

E5

METAL

C2

F1

MAIN FAULT

Cannot duplicate complaint - find no fault with rifle or trigger assembly. Trigger assembly and safety operate properly in all respects.

Trigger pull 5 1/4 pounds; over lift .0125"

PARTS

COMMENTS

Offer to return rifle as-is, or, offer to replace trigger assembly at \$200.00. A certificate of good-will, if that we both return confidence in the rifle scope in Calh.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTER

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV B

PPS 05180