

RECEIVING AND ESTIMATING REPORT

INITIAL LCS		CUSTOMER ORDER NO. 29480		COMMENTS			
DATE RECEIVED 01/04/91	DATE OPENED 01/10/91	DATE CODE BV 1-79	SERIAL NUMBER A6698848	MODEL AND GRADE 700 270 BDL		ORDER R 91-009	
ACCESSORIES W/STUDS		L/SIGHTS					

FROM:	SHIP TO:
VILLAGE SPORTS 2601 FERRAND MONROE LA 71201	VILLAGE SPORTS 2601 FERRAND MONROE LA 71201

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"The trigger when pulled is not firing the rifle"

do received, firing pin fell very slow. Inspection revealed trigger assembly and bolt stop contaminated with sticky, gummy residue. Sear-safety cam sticking to side plate of trigger cam. Trigger pull 54 #; sear lift .007".

PARTS	Clean present trigger assembly, if possible. If not, send quotation for $\pm$ normal cost, for replacement trigger as a gesture of good-will.					
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN	
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	

OFFICE COPY

RD6925 REV. 7/9

PPS 05239