

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R92-19772

INITIAL CUSTOMER ORDER NO.

ATTN: JIM STEKL

FPS

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
09/18/92	09/30/92	DM 9-65	172039		700 30-06 ADL
ACCESSORIES W/STUDS SCOPE BASE					

FROM:

WALKER, K C
3010 VILLAGE LANE
DEER PARK

TX 77536

SHIP TO:

WALKER, K C
3010 VILLAGE LANE
DEER PARKTX
77536

CUST NO: 067305 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

R638163:

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				F1
BOLT ASSY.		B3				F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Trigger assembly is contaminated with sticky, gummy substance (probably WD-40) to the point that the rear of safety pins are sticking to the side walls of the trigger frame. Rifle not operating properly as a result of some sticky firing pin follower on bolt. This condition is causing a delay in firing pin fall when trigger is pulled. Rifle has not been properly maintained.

PARTS

COMMENTS

After replacement trigger, rifle at normal cost, as gesture of good will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

PPS 05306