

Remington®



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

March 21, 1989

Mr. Loren Walling
3425 Lakeview Dr.
Lake Camanche Village
Lone, CA 95640

Dear Mr. Walling:

Your letter of recent date addressed to our Wilmington, DE location, referring to a Model 600, serial number 11249, has been forwarded to my office for handling.

We are conducting a trigger replacement program for certain concerned lots of Model 600 series firearms. The program has been nationally advertised over a period of years and involves complete fire assembly replacement for these rifles at no charge.

If you purchased your Model 600 second hand, the rifle may already have been updated. Therefore, if a "V" stamping appears on the left side of the trigger, the gun has had trigger replacement. If no "V" stamping appears on the left side of the trigger, the rifle requires trigger replacement.

Enclosed for your convenience is a list of California Remington trigger replacement stations, or you may return your rifle to our Arms Service Department here at Ilion, NY 13357 for correction.

If I can be of further service, please let me know.

Sincerely,

A handwritten signature in cursive script, appearing to read "D. O. Sanita".

D.O. Sanita

Product Service

DJS:tpp

encl.