

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

Dear Remington Customer:

Remington discovered, during routine testing, the possibility that a limited number of trigger assemblies for the Stainless Steel rifle may have missed a manufacturing process procedure. Although unlikely, THE CONDITION COULD CAUSE THE GUN TO MALFUNCTION AND ACCIDENTALLY DISCHARGE.

Our records indicate that you are a holder of one or more of these rifles in need of a replacement trigger. The serial number(s) of the concerned rifle(s) is listed on the enclosed form(s). **DO NOT USE THE RIFLE(S) UNTIL THE TRIGGER ASSEMBLY HAS BEEN REPLACED.**

We ask that you call the Special Service Department at 1-800-634-2459 (U.S. Residents), 1-800-634-5401 (Canadian Residents). They will direct you to the nearest Remington Authorized Gunsmith, who will be glad to replace the trigger assembly in your Model 700 Stainless Steel gun. To have your trigger replaced at the factory please send your gun via United Parcel Service, Transportation COD, to:

Remington Arms Company, Inc.
DEPT. SST
14 Hoefler Ave.
Ilion, NY 13357

Upon receipt of the gun, we'll quickly replace the trigger assembly, and return the firearm to you, prepaid.

If you have sold the gun, please provide the new owner information on the enclosed form. Then, return that form to this address using the postage paid envelope provided.

In returning your rifle(s) to the factory, please do the following:

1. Remove any non-Remington accessories including scope and scope rings. The scope mount can remain on the receiver.